



ADDENDUM TO INSTRUCTIONS 199R-9881
AFFECTING
HOLLEY CARBURETOR MODEL #'S

0-80450
0-80451
0-80454

VACUUM HOSE ROUTING

Due to changes in vacuum sources on these carb models, the hose routing has changed.

The Cannister Purge Port/Hose #4 now needs to be "T'd" into the Ported EGR Signal Port/Hose # 2.

A full listing and diagrams of hose connections can be found in the instruction sheet. All other connections are per instructions.

Holley Performance Products
P.O. Box 10360
Bowling Green, KY 42102-7360

Technical Service: 270-781-9741
Fax: 270-781-9772

199R-10252
Date: 4-23-01



ADDENDUM TO INSTRUCTIONS 199R-9881
AFFECTING
HOLLEY CARBURETOR MODEL #'S

0-80450
0-80451
0-80454

VACUUM HOSE ROUTING

Due to changes in vacuum sources on these carb models, the hose routing has changed.

The Cannister Purge Port/Hose #4 now needs to be "T'd" into the Ported EGR Signal Port/Hose # 2.

A full listing and diagrams of hose connections can be found in the instruction sheet. All other connections are per instructions.

Holley Performance Products
P.O. Box 10360
Bowling Green, KY 42102-7360

Technical Service: 270-781-9741
Fax: 270-781-9772

199R-10252
Date: 4-23-01